## **Mike Cantwell**

From: aplimgr@vcci.jp Sent:

Sunday, July 22, 2018 8:16 PM

To: Mike Cantwell

**Subject:** [VCCI Report of compliance]Certification of report

Report of Compliance

Report of Compliance has been accepted.

Report No.:2018068176 Acceptance No.:2017043658

<Contact person's information>

<Member's profile> Member number:1316

Company name: Network Engines Inc, DBA "NEI", & DBA "Unicom Engineering Inc."

Address:25 Dan Rd. Canton, MA 02021 USA

<Responsible person>

Department:Regulatory Compliance

Name:Mike Cantwell

E-mail:mike.cantwell@unicomengineering.com

<Contact person>

Address:25 Dan Rd Canton, Ma. 02021 USA

Department:Regulatory Compliance

Name:Mike Cantwell Phone:972-633-3417 FAX:972-633-3499

E-mail:mike.cantwell@unicomengineering.com

<Recipient of Acceptance Notice> Department:Regulatory Compliance

E-mail:mike.cantwell@unicomengineering.com

Applied VCCI Rule: VCCI 32-1

Reporting type:modify

General Name of Equipment:Server

Classification of Equipment and classification code: Class A / Classification code A2 Product type (Model No.):E-2900 R5 <Brand(1)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

<Brand(2)>

Name of the brand supplier:

Member number of the supplier: Product type (Model No.) of the branded Equipment: <Brand(3)>

Name of the brand supplier: Member number of the supplier: Product type (Model No.) of the branded Equipment: <Brand(4)>

Name of the brand supplier: Member number of the supplier: Product type (Model No.) of the branded Equipment: <Brand(5)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded Equipment:

Member number of a test laboratory:466 Sporton International Inc.

Name of the testing laboratory:

<Measurement facility registration number>

- 1) Radiated EMI measurement below 1GHz facility:R-1327 (10m)
- 2) Radiated EMI measurement above 1GHz facility:G-621 (3m)
- 3) Mains port conducted EMI measurement facility:C-1393
- 4) Wired network port and other port Conducted EMI measurement facility:T-1731
- 5) Article 15 registered laboratory:
- 6) This compliance verification test was conducted at the installation site of users.: Date of testing:2017-08-17 16-17 Aug, 2017 Serial No. of the test report:JV751117 Reason for addition/modification:Entered wrong classification code. Corrected to Class A (A2)

VCCI comment:	
VCCI Council	
URL : https://urldefense.proofpoint.com/v2/url?u=http-	
3Awww.vcci.jp_&d=DwICJg&c=euGZstcaTDllvimEN8b7jXrwqOf-	
v5A_CdpgnVfiiMM&r=hqz50oIUyy8rGEwORkrkKtLGXVE0ljiGuVYRM-	

I5N7s36anG851xb4zTN8k1ICSk&m=0gptBKd7FkbM5jM7R4aLHqseMsqFpBorZtZCOfaFLRM&s=ron8U-e3twmC5R0Ca14pZsVJ8JnA3DVOZd4EWQyQj18&e=

E-mail: aplimgr@vcci.jp

-----

This email has been scanned for spam and viruses. Visit the following link to report this email as spam: https://attseg.cloud-protect.net/index01.php?mod\_id=11&mod\_option=logitem&mail\_id=1532308546-nQpxaxuaP El&r address=mike.cantwell%40unicomengineering.com&report=